

Chartered Engineers, Valuer, Engineering Services, Structural Engineers, Retrofitting Consultant Chartered Engineers (Civil & Mechanical) Architects, Estimation Third Party Inspection, Project & Construction Management

Ref.363/CLA/SSC/PM-SHRI-07/Ambala Cantt

Er. C. L. Arora

AMIE, CE, FIV, FVA, Rtd. 5DO. Govt. of Haryana Regd, Valuer U/S 34 AB of Wealth Tax Act (Income Tax Dept.) Technical Inspection Authority MAEF (Govt. of India) Regd. Structural Engineer HSVDaGcdt06/02/20024 Panel valuer of SBI, PSU-Banks & Financial Institutions

The Principal/Manager, P.M. S H R I Govt. Senior Sec. School (Code 07) Ram Bagh Road, Ambala Cantt-133001 Haryana

SUBJECT-: STRUCTURAL STABILITY CERTIFICATE

R/Sir.

The School building of P.M. SHRI GOVT. SEN. SEC. SCHOOL (07) is situated at Ram Bagh Road Ambala Cantt. The building has been inspected on 06/02/2024 along-with School representative Math Master Sh. Sunil Kumar as per drawings provided by the School, The drawings has been prepared by Ar. ANU SHARMA Planners Den, 1st floor, Shakti Nagar Ambala city. (Copy of drawing is attached as Annexure –A)

The building is comprises of Administrative Block, IED-Source Room, Class rooms, Science Lab, mid-day Meal room, Computer lab, Gate & primary wing rooms etc.

- A. Total Area of plot of the School is 6519 Sq. yard = 1.44 Acre)
- B. Ground Floor Covered Area is 22552 Sft
- C. First Floor Covered Area is 6535.10 Sft.
- D. Total Covered Area is 22552 + 6535.10 = 29087.10 Sft

Administrative Block comprises of 4 rooms, Principal room, staff & data room etc. needs heavy repair & this block could not be used. Moreover, staff has informed, this block is already declared as abandoned by the Competent Authority.

Declaration:-

- 1. The undersigned has inspected the site on dt 06/02/2024
- 2. The undersigned does not have any direct / indirect interest in the above mentioned work.
- I am Chartered Engineer [India] of the Institution of Engineers [India]. My Chartered Engineer Certification No. is AM053000-2 of dated. 09.06.2015. is valid till date.
- I am Regd. as Structural Engineer with HSVP Panchkula (Govt. of Haryana) & my Regd. No. is <u>ADMN-2023/ER-46 & its endst. No.is A-4/2023/1824-827</u>

It is certified that I have personally examined the building of the School and structure of the building is safe & stable.

This certificate is valid for one year from the date of issue.

The periodical repair & Maintaince of building be done to avoid future deterioration

Place: - Ambala Cantt

Date: = 06/02/2824

Place - Ambala Canti Date - 06/02/2024 Principal
Principal
PM 2000
GM 8.8.8.8. Rambago Road
Ambado II

MASTER COPY

Chartered Engineer
AM053000-2 (Life time)

Carrie Circumstantia de la Companya de la Companya







Haryana PWD (B&R) Executive Engineer, Provincial Division No.1. PWD (B&R), Ambala Cantt - 133 001.

To

The Principal, Govt. Senior Secondary Scool, Rambagh Road, Ambala Cantt.

594

Dated: 13 2/2029

Subject:

Regarding Building Structure Safety Certificate.

Reference:

Your office Letter No. 153 dated 05.02.2024.

The school building i.e. P.M. SHRI GMSSS Rambagh Road, 07, Ambala Cantt Block -Ambala II has been visually inspected by the SDE P-6 alongwith JE incharge on dated 08.02.2024. The proof checked structural drawings of the building has not been provided by the school Authority during visit. The building is visually found safe. Hence, the school building safety certificate for year 2024 - 25 may be issued with following conditions except old Admn Block Building Marked (A):-

- 1. Water should not be allowed to stagnate around and on the roof of the Building.
- 2. If Building is found cracked from anywhere, the same should be got vacated immediately and same should be got repaired immediately.
- 3. Institution authorities will be responsible for safety of building from every angle and Fire-Fighting equipment's should be in functional condition.
- 4. If the building of the school is to be extended, the same should be approved from reputed Structural Engineer.
- 5. Adequate Fire safety may be adopted in the school campus building.
- 6. Authority will also ensure safety precautions from false ceiling, vitrified floor tiles & PVC paneling if provided.
- 7. NOC will be treated as cancelled by this office if the School violates any of the above points.
- 8. Proof Checked structural drawings of the building should be sent to this office for record within 1 month from the issuing of NOC.

DA/NIL

Executive Engineer, Provincial Division No.1, PWD B&R Br; Ambala Cantt.

Endst. No.

Dated:-

Copy of the above is forwarded to the Sub Divisional Engineer, Provincial Sub Division No. 6, PWD B&R Br; Ambala Cantt for information w.r.t. this office No. 71 dated 09.02.2024.

DA/ NIL



Executive Engineer, Provincial Division No.1, PWD B&R Br; Ambala Cantt.